



ROCKFORD FIRE DEPARTMENT INCIDENT UPDATE

Incident Information

Business Name: _____

Address of Incident: 1019 Bruce Street

Date of Incident: 11/20/2017

Time of Incident: 13:03

Type of Incident: Residential Structure Fire

Cause of Fire: Accidental

Estimated Loss: \$5,000

Injury Data

Civilian Injuries: 0

Civilian Deaths: 0

Fire Department Response

Engine(s): 3

Ladder(s): 2

District Chief(s): 2

Quint(s): _____

Ambulance(s): 1

Haz Mat Unit(s): 0

Boat(s): 0

Diver(s): 0

Other(s): 2

Total Firefighters: 23

Response Time: 4 min

Narrative

The Rockford Fire Department responded to a possible structure fire at a residential property. First arriving companies reported smoke showing from an attic vent on the gable end of a small single family residence. Fire Department members entered the building, exposed several sections of the ceiling, and located a small fire in the attic. The first arriving engine company quickly confined and extinguished the fire using a pre-connected attack line. An elderly man was home at the time of the fire and exited the building without any injuries. There were also no firefighter injuries. An investigator conducted an origin and cause investigation and determined the fire to be accidental and the result of electrical failure. The home sustained fire, smoke, and water damage. A building department Inspector determined the home to be uninhabitable until necessary repairs are completed. The Red Cross responded and assisted with temporarily relocating the displaced occupant of the home.

For additional information contact: 779-348-7172

Prepared by: Captain Luis Duran on 11/20/2017 at 20:40