



# ROCKFORD FIRE DEPARTMENT INCIDENT UPDATE

## Incident Information

Business Name: \_\_\_\_\_

Address of Incident: 3501 Modesto Drive

Date of Incident: 11/20/2017

Time of Incident: 00:26

Type of Incident: Residential Structure Fire

Cause of Fire: Accidental

Estimated Loss: \$20,000

## Injury Data

Civilian Injuries: 0

Civilian Deaths: 0

## Fire Department Response

Engine(s): 3

Ladder(s): 2

District Chief(s): 2

Quint(s): \_\_\_\_\_

Ambulance(s): 1

Haz Mat Unit(s): \_\_\_\_\_

Boat(s): \_\_\_\_\_

Diver(s): \_\_\_\_\_

Other(s): 1

Total Firefighters: 22

Response Time: 7 min

## Narrative

The Rockford fire department responded to a report of smoke in the basement. Upon arrival a fire was located burning in a hidden area around a wooden fireplace enclosure. Fire department members exposed all of the hidden areas of burning and were able to confine the fire to the chimney enclosure. The house will remain able to be occupied. All occupants were able to remove themselves from the building after being alerted by the smell of smoke and smoke alarms sounded. No injuries to firefighters or occupants were reported. This fire was accidental in nature and caused by fire extending to the house from the fireplace.

For additional information contact: 779-348-7172

Prepared by: Captain W. Hyde on 11/20/2017 at 02:50